

- Synchronous and induction machine inductances are functions of the rotor speed, therefore the coefficients of the differential equations (voltage equations) which describe the behavior of these machines are time-varying.
- A change of variables can be used to reduce the complexity of machine differential equations, and represent these equations in another reference frame with constant coefficients
- A change of variables which formulates a transformation of the 3-phase variables of stationary circuit elements to the arbitrary reference frame may be expressed

$$f_{pqdos} = K_s f_{abcs}$$

$$(f_{pqdos})^T = [f_{pqs} \quad f_{dls} \quad f_{sos}]$$

$$(f_{abcs})^T = [f_{as} \quad f_{bs} \quad f_{cs}]$$

$$K_s = \frac{2}{3} \begin{bmatrix} \cos \theta & \cos(\theta - \frac{2\pi}{3}) & \cos(\theta + \frac{2\pi}{3}) \\ \sin \theta & \sin(\theta - \frac{2\pi}{3}) & \sin(\theta + \frac{2\pi}{3}) \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{bmatrix}$$


$$\theta = \int_0^t \omega(t) dt + \theta(0)$$

$$(K_s)^{-1} = \begin{bmatrix} \cos\theta & \sin\theta & 1 \\ \cos(\theta - \frac{2\pi}{3}) & \sin(\theta - \frac{2\pi}{3}) & 1 \\ \cos(\theta + \frac{2\pi}{3}) & \sin(\theta + \frac{2\pi}{3}) & 1 \end{bmatrix}$$

"f" can represent either voltage, current, or flux linkage.

"s" indicates the variables, parameters and transformation associated with stationary circuits.

"w" represent the speed of reference frame.



$\omega = 0$ stationary reference frame

$\omega = \omega_e$ synchronously rotating reference frame

$\omega = \omega_r$ rotor reference frame (i.e. the reference frame is fixed on the rotor)

- f_{as} , f_{bs} and f_{cs} may be thought of as the direction of the magnetic axes of the stator windings.

- f_{qs} and f_{ds} can be considered as the direction of the magnetic axes of the "new" fictitious windings located on q - s and d - s axis which are created by the change of variables.

$$P_{abcs} = v_{as} i_{as} + v_{bs} i_{bs} + v_{cs} i_{cs}$$

$$P_{qdos} = P_{abcs}$$

$$= \frac{3}{2} (v_{qs} i_{qs} + v_{ds} i_{ds} + 2v_{os} i_{os})$$

- Stationary circuit variables transformed to the arbitrary reference frame.

- Resistive elements. For a 3-phase resistive circuit

$$v_{abcs} = \bar{r}_s i_{abcs}$$



$$i_{abcs} = (K_s)^{-1} i_{qdos}$$

$$v_{abcs} = (K_s)^{-1} v_{qdos}$$

$$(K_s)^{-1} v_{qdos} = \bar{r}_s (K_s)^{-1} i_{qdos}$$


$x(K_s)$

$$v_{qdos} = (K_s) \bar{r}_s (K_s)^{-1} i_{qdos}$$

$$v_{qdos} = \bar{r}_s i_{qdos}$$

$$(K_s) \bar{r}_s (K_s^{-1}) = r_s \quad \bar{r}_s = \begin{bmatrix} r_s & 0 & 0 \\ 0 & r_s & 0 \\ 0 & 0 & r_s \end{bmatrix}$$

• Inductive elements. For a 3-phase inductive circuit



$$\lambda_{abcs} = L_s \dot{\lambda}_{abcs} = \begin{bmatrix} L_s & 0 & 0 \\ 0 & L_s & 0 \\ 0 & 0 & L_s \end{bmatrix} \begin{bmatrix} \dot{\lambda}_{as} \\ \dot{\lambda}_{bs} \\ \dot{\lambda}_{cs} \end{bmatrix}$$

• In terms of the substitute variables, we have

$$\boxed{v_{qd0s} = K_s P [K_s^{-1} \lambda_{qd0s}]}$$

or $v_{qd0s} = K_s P [(K_s)^{-1}] \lambda_{qd0s} + K_s (K_s^{-1}) P \lambda_{qd0s}$

where,

$$P [(K_s)^{-1}] = W \begin{bmatrix} -\sin\theta & \cos\theta & 0 \\ -\sin(\theta - \frac{2\pi}{3}) & \cos(\theta - \frac{2\pi}{3}) & 0 \\ -\sin(\theta + \frac{2\pi}{3}) & \cos(\theta + \frac{2\pi}{3}) & 0 \end{bmatrix}$$

• After some work, we can show that

$$K_s P [(K_s)^{-1}] = W \begin{bmatrix} 0 & 1 & 0 \\ -1 & 0 & 0 \\ 0 & 0 & 0 \end{bmatrix}$$

$$v_{qdos} = K_s \underbrace{P [(K_s)^{-1}]}_{\omega \lambda_{dqs}} \lambda_{qdos} + K_s \underbrace{(K_s)^{-1} P}_{P} \lambda_{qdos}$$

$$v_{qdos} = \omega \lambda_{dqs} + P \lambda_{qdos}$$

where

$$(\lambda_{qds})^T = [\lambda_{ds} \quad -\lambda_{qs} \quad 0]$$

vector equation v_{qdos} can be expressed as

$$v_{qs} = \omega \lambda_{ds} + P \lambda_{qs}$$

$$v_{ds} = -\omega \lambda_{qs} + P \lambda_{ds}$$

$$v_{os} = P \lambda_{os}$$

where " $\omega \lambda_{ds}$ " term and " $\omega \lambda_{qs}$ " term are referred to as a "speed voltage" with the speed being the angular velocity of the arbitrary reference frame.

• When the reference frame is fixed in the stator, that is, the stationary reference frame ($\omega = 0$), the voltage equations for the three-phase circuit become the familiar time rate of change of flux linkage in abc reference frame.

For the three-phase circuit shown, L_s is a diagonal matrix, and

$$\lambda_{abc} = L_s \dot{\lambda}_{abc}$$

$$\lambda_{qdos} = K_s \underbrace{L_s K_s^{-1}}_{L_s} \dot{\lambda}_{qdos}$$

$$\lambda_{qdos} = L_s \dot{\lambda}_{qdos}$$


- For three-phase induction or synchronous machines,
 L_s matrix is expressed as

$$L_s = \begin{bmatrix} L_{ls} + L_{ms} & -\frac{1}{2}L_{ms} & -\frac{1}{2}L_{ms} \\ -\frac{1}{2}L_{ms} & L_{ls} + L_{ms} & -\frac{1}{2}L_{ms} \\ -\frac{1}{2}L_{ms} & -\frac{1}{2}L_{ms} & L_{ls} + L_{ms} \end{bmatrix}$$

L_{ls} : leakage inductance, L_{ms} : magnetizing inductance.

$$K_s L_s (K_s)^{-1} = \begin{bmatrix} L_{ls} + \frac{3}{2}L_{ms} & 0 & 0 \\ 0 & L_{ls} + \frac{3}{2}L_{ms} & 0 \\ 0 & 0 & L_{ls} \end{bmatrix}$$

- Consider the stator windings of a symmetrical induction or round rotor synchronous machine shown below:



$$r_s = \text{diag} [r_s \quad r_s \quad r_s]$$

$$L_s = \begin{bmatrix} L_s & M & M \\ M & L_s & M \\ M & M & L_s \end{bmatrix}$$

$$\bullet \quad L_s = L_{ls} + L_{ms} \quad , \quad M = -\frac{1}{2} L_{ms}$$

For each phase voltage, we write the following equations

$$V_{as} = r_s \dot{i}_{as} + P \lambda_{as}$$

$$V_{bs} = r_s \dot{i}_{bs} + P \lambda_{bs}$$

$$V_{cs} = r_s \dot{i}_{cs} + P \lambda_{cs}$$

$$V_{qdos} = K_s V_{abcs}$$

$$\dot{i}_{qdos} = K_s \dot{i}_{abcs}$$

$$\lambda_{abcs} = L_s \dot{i}_{abcs}$$

$$\dot{\lambda}_{qdos} = K_s \dot{\lambda}_{abcs}$$

In vector form,

$$V_{abcs} = r_s \dot{i}_{abcs} + P \lambda_{abcs}$$

• x by K_s

$$K_s V_{abcs} = K_s r_s (\dot{i}_{abcs}) + K_s P (\lambda_{abcs})$$

replace \dot{i}_{abcs} and λ_{abcs} using the transformation equations

$$K_s V_{abcs} = K_s r_s (K_s^{-1} \dot{i}_{qdos}) + K_s P [K_s^{-1} \dot{\lambda}_{qdos}]$$

$$V_{qdos} = r_s \dot{i}_{qdos} + \bar{\omega} \bar{\lambda}_{qdos}$$

or

$$V_{qs} = r_s \dot{i}_{qs} + \omega \lambda_{ds} + P \lambda_{qs}$$

$$V_{ds} = r_s \dot{i}_{ds} - \omega \lambda_{qs} + P \lambda_{ds}$$

$$V_{os} = r_s \dot{i}_{os} + P \lambda_{os}$$

where


$$\bar{\omega} = \omega \begin{bmatrix} 0 & 1 & 0 \\ -1 & 0 & 0 \\ 0 & 0 & 0 \end{bmatrix}$$

$$\lambda_{qs} = (L_s - M) i_{qs}$$

$$\lambda_{ds} = (L_s - M) i_{ds}$$

$$\lambda_{os} = (L_s + 2M) i_{os}$$

our equivalent circuit in arbitrary reference frame can be represented as



Commonly Used Reference Frames

$\omega = \text{unspecified}$ stationary circuit variables referred to the arbitrary reference frame. The variables are referred to as f_{qds} or f_{qs} , f_{ds} and f_{os} and transformation matrix is designated as K_s

$\omega = 0$ stationary circuit variables referred to the stationary reference frame. The variables are referred to as f_{qdos}^s or f_{qs}^s , f_{ds}^s and f_{os}^s and transformation matrix is designated as K_s^s

$\omega = \omega_r$ stationary circuit variables referred to a reference frame fixed in the rotor. The variables are referred to as f_{qds}^r or f_{qs}^r , f_{ds}^r and f_{os} and transformation matrix is designated as K_s^r .

$\omega = \omega_e$ stationary circuit variables referred to the synchronously rotating reference frame. The variables are referred to as f_{qds}^e or f_{qs}^e , f_{ds}^e and f_{os} and transformation matrix is designated as K_s^e .

$s \rightarrow$ stationary reference frame
 $f_{qds} \rightarrow$ d-q axes of stator variables

$r \rightarrow$ reference frame fixed on the rotor with speed of ω_r .
 $f_{qds} \rightarrow$ d-q axes of stator variables

$$\Theta_r = \int_0^t \omega_r(t) dt$$

$e \rightarrow$ synchronously rotating reference frame
 $f_{qds} \rightarrow$ d-q axes of stator variables

$$\Theta_e = \int_0^t \omega_e(t) dt$$

- Transformation of a balanced set.
- Consider a three-phase circuit which is excited by a balanced three-phase voltage set. Assume the balanced set is a set of equal-amplitude sinusoidal quantities which are displaced by 120° .

$$f_{as} = \sqrt{2} f_s \cos \theta_{ef}$$

$$f_{bs} = \sqrt{2} f_s \cos \left(\theta_{ef} - \frac{2\pi}{3} \right)$$

$$f_{cs} = \sqrt{2} f_s \cos \left(\theta_{ef} + \frac{2\pi}{3} \right)$$

$$f_{as} + f_{bs} + f_{cs} = 0 \quad (\text{balanced set})$$

$$\theta_{ef} = \int_0^t \omega_e(t) dt + \theta_{ef}(0)$$

θ_{ef} : Angular position of each electrical variable (voltage, current, and flux linkage) is θ_{ef} with the f subscript used to denote the specific electrical variable.

θ_e : Angular position of the synchronously rotating reference frame is θ_e .

θ_e and θ_{ef} differ only in the zero position $\theta_e(0)$ and $\theta_{ef}(0)$, since each has the same angular velocity of ω_e .

- f_{as} , f_{bs} and f_{cs} can be transformed to the arbitrary reference frame

$$\bar{f}_{qdos} = \bar{K}_s \bar{f}_{abcs}$$

After transformation, we will have.

$$f_{qs} = \sqrt{2} f_s \cos(\theta_{ef} - \theta)$$

$$f_{ds} = -\sqrt{2} f_s \sin(\theta_{ef} - \theta)$$

$$f_{os} = 0$$

- q and d variables form a balanced two-phase set in all reference frames except when $\omega = \omega_e$

$$f_{qs}^e = \sqrt{2} f_s \cos[\theta_{ef}(\omega) - \theta_e(\omega)]$$

$$f_{ds}^e = -\sqrt{2} f_s \sin(\theta_{ef}(\omega) - \theta_e(\omega))$$

- In q_s^e and d_s^e reference frame, sinusoidal quantities appear as constants or dc quantities.

Balanced Steady State Phasor Relationships

• For balanced steady state conditions ω_e is constant and sinusoidal quantities can be represented as phasor variables.

$$\begin{aligned}F_{as} &= \sqrt{2} F_s \cos[\omega_e t + \theta_{ef}(0)] \\ &= \text{Re}[\sqrt{2} F_s e^{j\theta_{ef}(0)} e^{j\omega_e t}]\end{aligned}$$

$$\begin{aligned}F_{bs} &= \sqrt{2} F_s \cos[\omega_e t + \theta_{ef}(0) - \frac{2\pi}{3}] \\ &= \text{Re}[\sqrt{2} F_s e^{j(\theta_{ef}(0) - 2\pi/3)} e^{j\omega_e t}]\end{aligned}$$

$$\begin{aligned}F_{cs} &= \sqrt{2} F_s \cos[\omega_e t + \theta_{ef}(0) + \frac{2\pi}{3}] \\ &= \text{Re}[\sqrt{2} F_s e^{j(\theta_{ef}(0) + 2\pi/3)} e^{j\omega_e t}]\end{aligned}$$

Balanced steady-state s-ds variables are

$$\begin{aligned}F_{rs} &= \sqrt{2} F_s \cos[(\omega_e - \omega)t + \theta_{ef}(0) - \theta(0)] \\ &= \text{Re}[\sqrt{2} F_s e^{j(\theta_{ef}(0) - \theta(0))} e^{j(\omega_e - \omega)t}]\end{aligned}$$

$$\begin{aligned}F_{ds} &= -\sqrt{2} F_s \sin[(\omega_e - \omega)t + \theta_{ef}(0) - \theta(0)] \\ &= \text{Re}[j\sqrt{2} F_s e^{j(\theta_{ef}(0) - \theta(0))} e^{j(\omega_e - \omega)t}]\end{aligned}$$

f_{as} phasor can be expressed as

$$\tilde{F}_{as} = F_s e^{j\theta_{ef}(0)}$$

for arbitrary reference frame ($\omega \neq \omega_e$),

$$\tilde{F}_{qs} = F_s e^{j(\theta_{ef}(t) - \theta_e(t))}$$

$$\tilde{F}_{ds} = j \tilde{F}_{qs}$$

selecting $\theta_e(0) = 0$,

$$\tilde{F}_{ds} = \tilde{F}_{qs}$$

- Thus, in all asynchronously rotating reference frames ($\omega \neq \omega_e$) with $\theta_e(0) = 0$, the phasor representing the ds variables is equal to the phasor representing the qs variables.

- In the synchronously rotating reference frame $\omega = \omega_e$, F_{qs}^e and F_{ds}^e can be expressed as

$$F_{qs}^e = \text{Re} \left[\sqrt{2} F_s e^{j(\theta_{ef}(t) - \theta_e(t))} \right]$$

$$F_{ds}^e = \text{Re} \left[j \sqrt{2} F_s e^{j(\theta_{ef}(t) - \theta_e(t))} \right]$$

let $\theta_e(0) = 0$, then


$$F_{qs}^e = \sqrt{2} F_s \cos(\theta_{ef}(t))$$

$$F_{ds}^e = -\sqrt{2} F_s \sin(\theta_{ef}(t))$$

$$\sqrt{2} \tilde{F}_{ds} = F_{qs}^e - j F_{ds}^e$$

since $\tilde{F}_{ds} = F_s e^{j(\theta_{ef}(t))} = F_s \cos(\theta_{ef}(t)) + j F_s \sin(\theta_{ef}(t))$

- Consider the stator winding of a symmetrical induction machine.



- Assume the stator winding is excited by a balanced 3-phase sinusoidal voltage set.

For phase a_s , we will have ($P = \frac{d}{dt}$)

$$V_{a_s} = r_s \dot{i}_{a_s} + L_s P i_{a_s} + M P i_{b_s} + M P i_{c_s}$$

For balanced conditions

$$V_{a_s} + V_{b_s} + V_{c_s} = 0$$

$$i_{a_s} + i_{b_s} + i_{c_s} = 0$$

$$M P i_{a_s} = -M P (i_{b_s} + i_{c_s})$$

$$V_{a_s} = r_s i_{a_s} + (L_s - M) P i_{a_s}$$

For steady-state conditions, $P = j\omega_e$

$$\tilde{V}_{a_s} = r_s \tilde{I}_{a_s} + [(L_s - M) j\omega_e] \tilde{I}_{a_s}$$

q_s and d_s voltage equations in the arbitrary reference frame, can be written as

$$V_{qs} = r_s i_{qs} + \omega \lambda_{ds} + p \lambda_{qs}$$

$$V_{ds} = r_s i_{ds} - \omega \lambda_{qs} + p \lambda_{ds}$$

$$\lambda_{qs} = (L_s - M) i_{qs}$$

$$\lambda_{ds} = (L_s - M) i_{ds}$$

Let $\omega = \omega_e$, then

$$V_{qs}^e = r_s i_{qs}^e + \omega_e \lambda_{ds}^e + p \lambda_{qs}^e$$

$$V_{ds}^e = r_s i_{ds}^e - \omega_e \lambda_{qs}^e + p \lambda_{ds}^e$$

$$\lambda_{qs}^e = (L_s - M) i_{qs}^e$$

$$\lambda_{ds}^e = (L_s - M) i_{ds}^e$$

For balanced steady-state conditions the variables in the synchronously rotating reference frame are constants, therefore, $p \lambda_{qs}^e$ and $p \lambda_{ds}^e$ are zero. Therefore, the above can be expressed as

$$V_{qs}^e = r_s I_{qs}^e + \omega_e (L_s - M) I_{ds}^e$$

$$V_{ds}^e = r_s I_{ds}^e - \omega_e (L_s - M) I_{qs}^e$$

Recall $\sqrt{2} \tilde{F}_{as} = F_{qs}^e - j F_{ds}^e$

Thus

$$\sqrt{2} \tilde{V}_{as} = V_{qs}^e - j F_{ds}^e$$

$$\sqrt{2} \tilde{V}_{as} = r_s I_{qs}^e + \omega_e (L_s - M) I_{ds}^e - j [r_s I_{ds}^e - \omega_e (L_s - M) I_{qs}^e]$$

Now $\sqrt{2} \hat{I}_{ds} = I_{qs}^e - j I_{ds}^e$

$$j \sqrt{2} \tilde{I}_{as} = I_{ds}^e + j I_{qs}^e$$

substituting in the above equation, we will have

$$\tilde{V}_{as} = [r_s + j \omega_e (L_s - M)] \tilde{I}_{as}$$