

Summary of dynamic Equations
of Induction machines

- machine dynamic equations in abc can be written as

$$\bar{V}_{abc} = P \bar{\lambda}_{abc} + r_s \dot{\bar{\lambda}}_{abc}$$

$$\bar{V}_{abc} = P \bar{\lambda}_{abc} + r_r \dot{\bar{\lambda}}_{abc}$$

- Flux linkages are

$$\begin{bmatrix} \bar{\lambda}_{abc} \\ \bar{\lambda}_{abc} \end{bmatrix} = \begin{bmatrix} \bar{L}_s & \bar{L}_{SR} \\ (\bar{L}_{SR})^T & \bar{L}_R \end{bmatrix} \begin{bmatrix} \dot{\bar{\lambda}}_{abc} \\ \dot{\bar{\lambda}}_{abc} \end{bmatrix}$$


- $\dot{\lambda}'_{abc} = \frac{N_r}{N_s} \dot{\bar{\lambda}}_{abc}$

- $V'_{abc} = \frac{N_s}{N_r} \bar{V}_{abc}$

- $\lambda'_{abc} = \frac{N_s}{N_r} \bar{\lambda}_{abc}$

$$[\bar{L}_s] = \begin{bmatrix} L_{ss} + L_{ms} & -\frac{1}{2} L_{ms} & -\frac{1}{2} L_{ms} \\ -\frac{1}{2} L_{ms} & L_{ss} + L_{ms} & -\frac{1}{2} L_{ms} \\ -\frac{1}{2} L_{ms} & -\frac{1}{2} L_{ms} & L_{ss} + L_{ms} \end{bmatrix}, \quad [\bar{L}_R] = \begin{bmatrix} L_{rr} + L_{mr} & -\frac{1}{2} L_{mr} & -\frac{1}{2} L_{mr} \\ -\frac{1}{2} L_{mr} & L_{rr} + L_{mr} & -\frac{1}{2} L_{mr} \\ -\frac{1}{2} L_{mr} & -\frac{1}{2} L_{mr} & L_{rr} + L_{mr} \end{bmatrix}$$

$$[\bar{L}_{SR}] = L_{SR} \begin{bmatrix} \cos \theta_r & \cos(\theta_r + \frac{2\pi}{3}) & \cos(\theta_r - \frac{2\pi}{3}) \\ \cos(\theta_r - \frac{2\pi}{3}) & \cos \theta_r & \cos(\theta_r + \frac{2\pi}{3}) \\ \cos(\theta_r + \frac{2\pi}{3}) & \cos(\theta_r - \frac{2\pi}{3}) & \cos \theta_r \end{bmatrix}$$






Fig. 1 Axis of 2-pole, 3-phase symmetrical machine

• Transformation equations are:

$$\bar{f}_{qdos} = T_s(\theta) \bar{f}_{abcs}$$

$$T_s(\theta) = \frac{2}{3} \begin{bmatrix} \cos \theta \cdot \cos(\theta - \frac{2\pi}{3}) & \cos(\theta + \frac{2\pi}{3}) \\ \sin \theta \cdot \sin(\theta - \frac{2\pi}{3}) & \sin(\theta + \frac{2\pi}{3}) \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{bmatrix}$$

$$\bar{f}_{qdor} = T_r(\beta) \bar{f}_{abcr}$$

$$T_r(\beta) = \frac{2}{3} \begin{bmatrix} \cos \beta \cdot \cos(\beta - \frac{2\pi}{3}) & \cos(\beta + \frac{2\pi}{3}) \\ \sin \beta \cdot \sin(\beta - \frac{2\pi}{3}) & \sin(\beta + \frac{2\pi}{3}) \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{bmatrix}$$

$$[T_s(\theta)]^{-1} = \begin{bmatrix} \cos \theta & \sin \theta & 1 \\ \cos(\theta - \frac{2\pi}{3}) & \sin(\theta - \frac{2\pi}{3}) & 1 \\ \cos(\theta + \frac{2\pi}{3}) & \sin(\theta + \frac{2\pi}{3}) & 1 \end{bmatrix}$$

$$[T_r(\beta)]^{-1} = \begin{bmatrix} \cos \beta & \sin \beta & 1 \\ \cos(\beta - \frac{2\pi}{3}) & \sin(\beta - \frac{2\pi}{3}) & 1 \\ \cos(\beta + \frac{2\pi}{3}) & \sin(\beta + \frac{2\pi}{3}) & 1 \end{bmatrix}$$

$$\beta = \theta - \theta_r$$

- machine dynamic equations from a reference frame with an angular speed ω of rotating d-q axes can be written as

$$v_{qs} = r_s \dot{i}_{qs} + P \lambda_{qs} + \omega \lambda_{ds}$$

$$v_{ds} = r_s \dot{i}_{ds} + P \lambda_{ds} - \omega \lambda_{qs}$$

$$v_{os} = r_s \dot{i}_{os} + P \lambda_{os}$$

$$v_{qr} = r_r \dot{i}'_{qr} + P \lambda'_{qr} + (\omega - \omega_r) \lambda'_{dr}$$

$$v_{dr} = r_r \dot{i}'_{dr} + P \lambda'_{dr} - (\omega - \omega_r) \lambda'_{qr}$$

$$v_{or} = r_r \dot{i}'_{or} + P \lambda'_{or}$$

$$\omega = \frac{d\theta}{dt} \quad \omega - \omega_r = \frac{d}{dt} (\beta) = \frac{d}{dt} (\theta - \theta_r)$$

- Flux linkage equations can be written as

$$\lambda_{qs} = L_{ls} \dot{i}_{qs} + L_{mq} (\dot{i}_{qs} + \dot{i}'_{qr})$$

$$\lambda_{ds} = L_{ls} \dot{i}_{ds} + L_{md} (\dot{i}_{ds} + \dot{i}'_{dr})$$

$$\lambda_{os} = L_{ls} \dot{i}_{os}$$

$$\lambda'_{qr} = L'_{lr} \dot{i}'_{qr} + L_{mq} (\dot{i}_{qs} + \dot{i}'_{qr})$$

$$\lambda'_{dr} = L'_{lr} \dot{i}'_{dr} + L_{md} (\dot{i}_{ds} + \dot{i}'_{dr})$$

$$\lambda'_{or} = L'_{lr} \dot{i}'_{or}$$

$$T_e = \frac{3}{2} (P/2) (\lambda_{os} \dot{i}_{qs} - \lambda_{qs} \dot{i}_{os})$$





Fig. 3 Equivalent circuits of a 3-phase, symmetrical induction machine with rotating d-q axis at speed of ω

- When $\omega \neq 0$ equal to zero, the reference frame is fixed in the stator ($d^s - q^s$ ref-frame)
- When ω is equal to ω_e , the reference frame is fixed on the synchronously rotating reference frame.
- When ω is equal to ω_r , the reference frame is fixed in the rotor. That is, the reference frame is rotating at speed of ω_r .

Axes transformation.

- Consider the stationary reference where the q^s -axis is coincident with the a^s -axis. That is $\theta = 0$



Stationary $a^s - b^s - c^s$ to $d^s - q^s$ axes transformation.



- From the transformation equations with $\theta = 0$, we will have,

$$V_{ds} = V_{qs}^s$$


$$V_{bs} = -\frac{1}{2} V_{qs}^s - \frac{\sqrt{3}}{2} V_{ds}^s$$

$$V_{cs} = -\frac{1}{2} V_{qs}^s + \frac{\sqrt{3}}{2} V_{ds}^s$$

$$V_{qs}^s = \frac{2}{3} V_{ds} - \frac{1}{3} V_{bs} - \frac{1}{3} V_{cs} = V_{ds}$$

$$V_{ds}^s = -\frac{1}{\sqrt{3}} V_{bs} + \frac{1}{\sqrt{3}} V_{cs}$$

- Voltages in the stationary d^s-q^s frame can be converted to the synchronously rotating d^e-q^e frame using the fig. below:



Stationary d^s-q^s axes to Synchronously rotating d^e-q^e axes transformation.

$$V_{qs}^e = V_{qs}^s \cos \omega t - V_{ds}^s \sin \omega t$$

$$V_{ds}^e = V_{qs}^s \sin \omega t + V_{ds}^s \cos \omega t$$

or

$$V_{qs}^s = V_{qs}^e \cos \omega t + V_{ds}^e \sin \omega t$$

$$V_{ds}^s = -V_{qs}^e \sin \omega t + V_{ds}^e \cos \omega t$$

• For example, assume

$$V_{as} = V_m \cos \omega t$$

$$V_{bs} = V_m \cos (\omega t - 120^\circ)$$

$$V_{cs} = V_m \cos (\omega t + 120^\circ)$$

$$\bullet V_{qs}^s = \frac{2}{3} V_{as} - \frac{1}{3} V_{bs} - \frac{1}{3} V_{cs} = V_{as} = V_m \cos \omega t$$

$$\bullet V_{ds}^s = -\frac{1}{\sqrt{3}} V_{bs} + \frac{1}{\sqrt{3}} V_{cs} = -V_m \sin \omega t$$

$$\bullet V_{qs}^e = V_{qs}^s \cos \omega t - V_{ds}^s \sin \omega t$$

$$= V_m \cos \omega t \cos \omega t - (-V_m \sin \omega t) (\sin \omega t)$$

$$= V_m$$

• The above relations verify that the sinusoidal variables appear as dc quantities in a synchronously rotating reference frame.

Induction machine Steady-State Equivalent circuit.

- consider stationary reference frame
 $\omega = 0$

$$V_{qs}^s = r_s i_{qs}^s + P \lambda_{qs}^s$$

$$\lambda_{qs}^s = L_{ss} i_{qs}^s + L_{mq} i_{qr}^{is}, \quad L_{ss} = L_{ls} + L_{mq}$$

$$V_{ds}^s = r_s i_{ds}^s + P \lambda_{ds}^s$$

$$\lambda_{ds}^s = L_{ss} i_{ds}^s + L_{ms} i_{dr}^{is}, \quad L_{ss} = L_{ls} + L_{md}$$

$L_{ms} = L_{md} = L_{mq}$

$$V_{qr}' = r_r' i_{qr}' - \omega_r \lambda_{dr}' + P \lambda_{qr}'$$

$$V_{dr}' = r_r' i_{dr}' + \omega_r \lambda_{qr}' + P \lambda_{dr}'$$

$$\lambda_{dr}' = L_{rr}' i_{dr}' + L_{ms} i_{ds}^s$$

$$L_{rr}' = L_{lr}' + L_{ms}$$

$$\lambda_{qr}' = L_{rr}' i_{qr}' + L_m i_{qs}^s$$

- Assume v_{as} , v_{bs} and v_{cs} are sinusoidal voltages, then
 $P = \frac{1}{2} \omega_e$.

$$\rightarrow \tilde{V}_{qs}^s = (r_s + j\omega_e L_{ss}) \tilde{I}_{qs}^s + j\omega_e L_{ms} \tilde{I}_{qr}^s$$

$$\tilde{V}_{ds}^s = (r_s + j\omega_e L_{ss}) \tilde{I}_{ds}^s + j\omega_e L_{ms} \tilde{I}_{dr}^s$$

$$\rightarrow \tilde{V}_{qr}^s = (j\omega_e L_{ms}) \tilde{I}_{qs}^s - \omega_r L_{ms} \tilde{I}_{dr}^s + (r_r' + j\omega_e L_{rr}') \tilde{I}_{qr}^s - \omega_r L_{rr}' \tilde{I}_{qr}^s$$

$$\tilde{V}_{dr}^s = \omega_r L_{ms} \tilde{I}_{qs}^s + j\omega_e L_{ms} \tilde{I}_{ds}^s + \omega_r L_{rr}' \tilde{I}_{qr}^s + (r_r' + j\omega_e L_{rr}') \tilde{I}_{dr}^s$$

Recall $\tilde{F}_{qs}^s = -j \tilde{F}_{ds}^s$

$$\tilde{F}_{qr}^s = -j \tilde{F}_{dr}^s$$

- we can use either the q_s^s and q_r^s or d_s^s and d_r^s equations to obtain the steady-state phase equation and equivalent circuit of induction machine. we will use q_s^s and q_r^s voltage equations

$$\bullet V_{qs}^s = [r_s + j(X_{es} + X_{ms})] \tilde{I}_{qs}^s + jX_{ms} \tilde{I}_{qr}^s$$

$$L_{ss} = L_{es} + L_{ms} \quad X_{ms} = \omega_e L_{ms}, L_{es} = \omega_e L_{es}$$

- Rewrite

$$\omega_r L_{ms} = \frac{\omega_r}{\omega_e} \omega_e L_{ms} = \frac{\omega_r}{\omega_e} X_{ms}$$

$$\bullet L'_{rr} = L'_{er} + L_{ms}$$

$$\bullet \omega_r L'_{rr} = \frac{\omega_r}{\omega_e} \omega_e (L'_{er} + L_{ms}) = \frac{\omega_r}{\omega_e} (X'_{es} + X_{ms})$$

• we can rewrite $V_{qr}^{'s}$ as

$$V_{qr}^{'s} = j X_{ms} I_{qs}^s - \overbrace{\frac{\omega_r}{\omega_e} X_{ms} \tilde{I}_{ds}^s}^A +$$

$$\begin{aligned} & [r'_r + j(X'_{er} + X_{ms})] I_{qr}^{'s} \\ & - \underbrace{\frac{\omega_r}{\omega_e} (X'_{er} + X_{ms}) \tilde{I}_{dr}^{'s}}_B \end{aligned}$$

Recall

$$\tilde{F}_{qr}^s = -j F_{ds}^s$$

$$\tilde{F}_{ds}^s = j F_{qr}^s$$

$$F_{qr}^{'s} = -j \tilde{F}_{dr}^{'s}$$

$$\tilde{F}_{dr}^{'s} = j F_{qr}^{'s}$$

• replace \tilde{I}_{ds}^s and $\tilde{I}_{dr}^{'s}$ with \tilde{I}_{qs}^s and $\tilde{I}_{qr}^{'s}$

• Term A

$$- \frac{\omega_r}{\omega_e} X_{ms} \tilde{I}_{ds}^s = - \frac{\omega_r}{\omega_e} j X_{ms} \tilde{I}_{qs}^s$$

• Term B

$$- \frac{\omega_r}{\omega_e} (X'_{er} + X_{ms}) \tilde{I}_{dr}^{'s} = -j \frac{\omega_r}{\omega_e} (X'_{er} + X_{ms}) \tilde{I}_{qr}^{'s}$$

Then

$$V_{qr}^{i's} = jX_{ms} \tilde{I}_{qs}^s - \frac{\omega_r}{\omega_e} jX_{ms} \tilde{I}_{qs}^s + \\ [r_r' + j(X_{lr}' + X_{ms})] \tilde{I}_{qr}^{i's} \\ - j \frac{\omega_r}{\omega_e} (X_{lr}' + X_{ms}) \tilde{I}_{qr}^{i's}$$

or

$$V_{qr}^{i's} = jX_{ms} \left(1 - \frac{\omega_r}{\omega_e}\right) \tilde{I}_{qs}^s + [r_r' + j\left(1 - \frac{\omega_r}{\omega_e}\right)(X_{lr}' + X_{ms})] \tilde{I}_{qr}^{i's}$$

$$V_{qr}^{i's} = jX_{ms} \left(\frac{\omega_e - \omega_r}{\omega_e}\right) \tilde{I}_{qs}^s + [r_r' + j(X_{lr}' + X_{ms}) \times \\ \left(\frac{\omega_e - \omega_r}{\omega_e}\right)] \tilde{I}_{qr}^{i's}$$

let

$$s = \frac{\omega_e - \omega_r}{\omega_e}$$

RECALL $\tilde{F}_{qs}^s = \tilde{F}_{as}$

$$\tilde{F}_{qr}^{i's} = \tilde{F}_{ar}'$$

then V_{qs}^s can be written as

$$\tilde{V}_{as} = [r_s + j(X_{ls} + X_{ms})] \tilde{I}_{as} + jX_{ms} \tilde{I}_{ar}'$$

or

$$\hat{V}_{as} = (r_s + jX_{es}) \hat{I}_{as} + jX_{ms} (\hat{I}_{as} + \hat{I}'_{ar})$$

divide \hat{V}'_{qr} by S

$$\frac{\hat{V}'_{qr}}{S} = jX_{ms} (\hat{I}'_{qs} + \hat{I}'_{qr}) + \left[\left(\frac{r'_r}{S} + jX'_{er} \right) \right] \hat{I}'_{qr}$$

RECALL

$$\hat{I}'_{qr} = \hat{I}_{ar} \quad \hat{I}'_{qs} = \hat{I}_{as}$$


$$\hat{V}'_{qr} = \hat{V}'_{ar}$$

$$\frac{\hat{V}'_{ar}}{S} = \left(\frac{r'_r}{S} + jX'_{er} \right) \hat{I}'_{ar} + jX_{ms} (\hat{I}_{as} + \hat{I}'_{ar})$$

where

$$X_{es} + X_{ms} = \omega_e L_{ss} = \omega_e (L_{es} + L_{ms})$$

$$X'_{er} + X_{ms} = \omega_e L'_{rr} = \omega_e (L'_{er} + L_{ms})$$



Equivalent circuit of an induction machine

• For short-circuited rotor $V'_{ar} = 0$